


RIDLER TRAIL STRUCTURES REPAIR PROJECT



Inspection date: October 22, 2025

Compiled by: Jason Berlin, Senior Building Inspector & Maria Sandberg, Planning and Parks Coordinator

Infrastructure Summary

The Ridler Trail includes the following structures that need repairs and upgrades.

Infrastructure Type/Structure #	Qty	General Description / Function/Work needed
Outhouses 4,13	2	Vault-style toilet facilities located at two of the three shelters (#2 and 12). #4 Door handle and lock required, door needs adjustment. #13 Roofing cracked needs replacement, door lock needs adjustment.
Shelters 2,12,14	3	Roofed wooden structures serving as day-use or emergency shelters for trail users. Additional lateral bracing required at top of posts of all three shelters
Boardwalk with bench 17	1	Boardwalk in overall good condition. Some general maintenance required to one deck board and skirting boards. Bench attached to trees, removal required as detaching from tree trunk.
Bridges 18	1	Wooden pedestrian/bike bridge with guard rails crossing over stream and wetland area.

Infrastructure Details

Structure 2 - Shelter, 8'x 14'

In very good condition, constructed of pressure treated materials

Additional lateral bracing required at top of posts



Structure 4 - Outhouse, 4'x4' with 4'x4' entry landing

In very good condition, constructed of pressure treated materials. Ample volume left in pit privy

Door handle and lock required, door needs adjustment.



Structure 12 - Shelter 8'x14' with deck 7'x14'

In very good condition, constructed of pressure treated materials

Additional lateral bracing required at top of posts, brushing around structure required



Structure 13 - Outhouse, 4'x4' with 2'x4' entry landing

In very good condition, constructed of pressure treated materials. Ample volume left in pit privy
Roofing cracked needs replacement, door lock needs adjustment.



Structure 14 - Shelter, 8'x 14'

In very good condition, constructed of pressure treated materials

Additional lateral bracing required at top of posts



Structure 17 - Boardwalk 4'x59' with bench 2'x8'

Boardwalk in overall good condition some general maintenance required to one deck board and skirting boards. Bench attached to trees, removal required as detaching from tree trunk.



Structure 18 - Bridge, 8'x30'

Very good condition, constructed of pressure treated materials

Guard rail broken from tree damage to be removed and replaced. Gaps at edge bridge deck to be filled in to avoid possible spots for injury.

